

CPM Playgrounds Ltd

For complete playground care

CPM Playgrounds Ltd

.34 Firecrest

Letchworth Garden City

Herts

SG6 4YF

Tel:07770 326499 or
01462 635667

E-mail:cpm.playgrounds@hotmail.co.uk

Kimpton Parish Council

Kimpton Memorial Hall

Hall Lane

KIMPTON

Herts

SG4 8BR

Operational Playground Inspection Report

Site: Recreation Ground Date: 20th March 2023 Time:9.50 am Inspected by: A Bunker

Site and Ancillary Items:

Fencing

1.2 m high mesh with wooden posts and rails on eastern side as divider between ball games area. Several post loose in the ground . Monitor

Gate

There is no gate on this scheme, but there are entrance gates to the recreation ground from the High Street, both vehicular and pedestrian. Findings – Good Order

Seats

2no timber slatted seats on metal frames, mounted on concrete slabs. Findings – Good Order.

But showing signs of rot

Picnic Table

2no recycled plastic and steel tables. Findings – Good Order, but x 1 loose in ground. Loose

table has had wooden wedges added to stop it moving,

Litter Bins

1no timber slatted surround with open top steel liner. Findings – Good Order

Signs

Sign on the wall at entrance from the High Street – Peeling off

Sign on gate – Good Order

Site

A spacious open play area. Findings – Good Order

Play Equipment

Kompan moments play house -

Findings -Good Order. 1 x cap has slight fire damage. Roof is showing signs of rot

Tic Tac Toe

Findings Good Order

Kompan crazy daisy -

Findings – Good Order

Proludic see-saw -

Findings – Good Order

Wicksteed 8ft.four seat swing

Traditional type 2 cradles 2 flat seats -

Findings – Good Order,

Wicksteed tom thumb unit

Toddler playhouse/slide -

Findings – The steering wheel is wobbly and should be monitored.

Kompan supernova -

Findings – Good Order

Kompan spica -

Findings – Good Order

Kompan spinning bowl -

Findings – Good Order

Monster nest pendulum swing	Good Order
Monster roll over bars -	Findings – Good Order
SMP tornado twirl -	Findings – Good Order
Concord rope climber -	Findings- Good Order. CPM removed sharp wire on rope

Safety Surfaces

The bark pits should all be 300 mm deep.

Bark pits

Kompan Spica	Findings –Good Order
Kompan crazy daisy	Findings- Good Order
Proludic seesaw	Findings –Good Order
Kompan supernova	Findings – Good Order
Kompan spinning bowl	Findings – Good Order
Monster roll over bars	Findings- Good Order
SMP tornado twirl	Findings—Good Order
Monster nest pendulum swing	Findings – Good Order
Tyre Walk	Findings- Tyres removed

Grass mats and tiles

Findings – There is a trip hazard on both sides of the Swing base tiles. This should be filled in with soil and grass seed

Proldic Pull Up Bars	Findings Good Order
Proludic Pendulum And Twist	Findings Good Order
Proludic Elliptical	Findings Handles loose on top spindle . CPM tightened fixings
Proludic Spinning Bicycle	Findings Good Order

Comments

There is movement in the swing bushes but it is not the swing bushes that are worn , it is the holes in the metal hangers that the bushes locate into.

Signed.....A Bunker.....

Date 26th March 2023