Kimpton Rights of Way Working Party Status Report, September 2020, draft v2

Item

1. Introduction

Although in March we had an impromptu meeting with our new HCC Access Officer, Andrew Burton, subsequent communication has proved difficult. In particular, we did not receive any information at all about the first maintenance cut of the year and we abandoned our planned working group meeting for early June. We did receive some information, though rather belated and incomplete, concerning the recent second cut and much of this present report is based on a survey of the work done recently.

Meanwhile, we have done what we could locally, with the additional support of the Bench Working Party. But major issues remain on which we are dependent for the support of HCC.

2. Status of Kimpton rights of way - overview

Once again the upside of another summer drought has been that there has not been too much overgrowth. So, as last year, there are not so many problems with be-nettled kissing gates and the like.

Maintenance

Revising slightly what I said this time last year, HCC's new maintenance contract seems to be working 'more or less' OK. Given the difficulty we have had getting information about the timing of the work, it has been difficult to check it and report back in a timely manner so shortcomings could be corrected. Detailed report below.

Ploughing (etc.)

Deep ploughing has not been quite so problematic this year. The main problem has been early growth, when the paths have not been reinstated or otherwise made clear. The tall waymarks may help a little but are not a complete solution. Some paths are almost impassable because of the growing crop.

Signage

Generally fine. Usual issues: some finger-posts obscured by overgrowth from hedges; faded waymarks that can be refreshed with stick-on copies; and a few rotted waymark posts. (Also see above re ploughing and tall waymarks.) Some 'white-topped' waymarks have been refreshed to help with cross-field paths.

3. Maintenance: 2020 second cut review

Annex 1 comprises an annotated version of the 'schedule' for those sections of our rights of way that are to be either mown or strimmed. In the right hand columns are indications of whether what has been done has been checked yet and a summary of any findings. Some of these are amplified in the notes below following the general findings.

General


Mostly the cuts were satisfactory. Shortcomings were in parts that were not done at all and, along some stretches, the cut was clearly patchy and often nowhere near low enough to meet the specification (75mm.). This was particularly the case where the grass (etc.) had been long. This suggests that the mower operator was unfamiliar with the technique for cutting long grass or that they were in too much of a hurry. Either way, they seem to have disregarded the specification. In most places where this was evident it is not too serious since the route is clear and footfall will deal with the rest.

FP2

This is odd. Year on year the new contractors seems to ignore the headland just south of the steps from the recreation ground.



FP14



The narrowness of this path has been a problem for a long time, exacerbated by overgrowth from bushes planted hard up against it on the northern side. The contractors note "hedge not cut". It is worse than that. At the eastern end, near Ayot church, holly almost blocks the way.

FP17

This was added to the schedule a year or two ago but on the 3rd September it was not marked as done and it had clearly not been done by the 18th September. The gateway in particular was *extremely* difficult to get through – apart from the nettles along the way. And the main headland appeared untouched.





FP47

Some thanks are due here. This path goes from Peter's Green Village Hall to the 'unclassified county road' at Chiltern Green. The Chiltern Green end lies in Bedford where it is not a recognised right of way and was never maintained (one of many oddities of the move to 'definitive statements'). A year or two ago HCC agreed to take on the maintenance of that southernmost stretch across Chiltern Green and I am glad to report that this is still happening: the path no longer just stops short of Chiltern Green facing an impenetrable barrier of bramble and brush.



4. Other non-'maintenance' issues with specific rights of way

Note .. this may not be complete, given time constraints

FP22: in March we asked Andrew Burton if he would talk to the residents of Cuckold's Cross Cottage but the barbed wire is *still* there:



FP26: the kissing gate at Hoo Cottages end is badly overgrown with holly and the rotted waymark is just loosely propped against the fence.





FP28 & FP29: the most depressing paths in the parish.

The saga of the route of FP29 through (or around) the Bothy and Keeper's Cottage drags on. 35 (?) years now. Andrew Burton said in March that he would look into the now long-promised enforcement action and we await his report back.

The FP28 waymark on the corner of Keeper's Cottage is in a still worse state. And the barbed wire is *STILL* there. Last year's photo will suffice: no change (for the good).



And the cross-field section has not been reinstated. Again.



Without the waymark, this is even worse than it was.

Kissing gate at junction of FP28 & FP29:


The barber wire on the right is just WRONG! (And, I believe, illegal.)



BR39 (Skegsbury Lane):

We have heard no more of the worrying proposal to upgrade this to a Restricted Byway.

In April we expressed concern that one or more of the adjacent residents were encroaching on this ancient bridleway. We warned HCC that this was happening and asked if we could have a detailed (1:1250) map showing the precise boundaries of the public and private land. We understood that the Highways Department charges a small fee for this and said that we were (and still are) prepared to pay that. Andrew Burton said he would investigate and discuss it with his colleagues. We await his response. Unfortunately, since then, the encroachment has got worse.



RB50 (also Wheathampstead 8): this is almost impassable with bramble and nettle:

Getting through it was very painful with stings and quite a bit of blood.

BR51 & FP53: rotten waymark at their junction not yet fixed. Something we could do ourselves but not yet arranged.

4. Parish Paths Partnership (P3)

We had agreement to our P3 application for last year and further agreement to vire the budget in order to purchase kissing gates for St Paul's Walden stretch north of FP21 (PW20?). Andrew Burton had said in March that he could recommend a supplier if we would provide dimensions, which we did in July. We await his response.

5. Volunteer support

We have been given to understand that although the 'old' means of volunteer support through CMS has changed, such support is still available. In July we sent to Andrew

Burton details of support we would like to improve the access at the start of FP10 between Cooper's Hill and the field above. We await his response.

7. Kimpton public rights of way map

Bob still has to get reprints of an updated map.

a
Ε
Ξ
=
S
>
é
=
7
2
¥
_
O
7
⊆
7
∞
$\overline{}$
0
7

Checking comments.	✓ 0K	V OK except (again!) headland between FP1 & FP8	XO <u>→</u>	✓ OK	✓ OK (if not to spec.)	✓ OK (ditto)	<u>✓ 0K</u>	✓ OK	yo ∕	2		XO >	surface OK but hedge overgrowth NOT OK	✓ NOT OK: headland not done; gate nr impassable	V OK (not 'maintenance' but note barbed wire STILL!!)	V OK - access fm road good	XO <u>→</u>	✓ OK			Xo >	XO ✓) V	_	✓ Headland OK			4: 30	OK-ish	OK	✓ OK (contractor's note "canopy collapsing") ?	✓ OK	✓ OK incl P's Gn end of CBW)	✓ OK-ish	✓ OK	5	✓ OK (thanks to residents?)	✓ Good! (Incl. Ch. Gn end, thanks to Tom G)	✓ OK				ОК	MO M	
gth Description	417 SW cnr of Rec. to Ballslough Hill	232 Jn. w FP7 to Ballslough Hill (needs clarification)	249 ALL - apart from badger sett	160 Hall Fm gate toward PP start (see also final item)		189 ALL (n.b. as far as FP02)	331 fm jn w FP01 to Hall Lane.	289 Only from BR5 to somewhere short of FP61 ????	182 Headland by copse NW of Hall Farm		315 Western sretch - shared w Wheathampstead		304 ALL	213 ALL	456 ALL	273 Round The Bungalow then to start of x-field part	210 Headland to N of the field as far as the farm track	$122 {\sf headland}$ by side of Valentine's Grove	81 NE of Hoopark Wood; S of Mare's Dell; gate @ E end	210 Headland along Mare's Dell		13 Northern access to FP26			266 Jn w FP28 to start of disputed stretch			50 ALL 57 Start on Vinnator Boad to NE comor of conco	272 Start of Milipion Road to NE connet of copse		_		236 Ramridge Lane to Oaktree Garage	233 From new Ramridge S to corner of wood (Jn FP42)	268 NE cnr Bishey Wood to x-fld part to BR41			328 From gate by chapel to Chiltern Green			Porters End Lane to start of gravel drive		526 Headlands after x-field, to Whiteways Bottom	645 Kimpton bit from S edge of Hurst Wood: ALL	O 11 - 11 V 1 - 2 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
Dist Length To (m)		512	249	811							652		304	213			820	771	431		865	1,052		521				00						_	377		285							645	CC
Dist I From (m)	172	280	0	651	0	0	0	322		$\overline{}$	336	<i>د</i> .	0	0	0	0	641	029	320	648				0	0	0	0	D	0 0	185	١.	309	0	41	109	185	0	39	0			210	328	0	c
Comments																																													
Status	단	FP	dЫ	BR	ΕР	FP	FP	FP	ЬP	FP	단	ΕР	FP	FP	ЬP	FP	ЬP	FP	FP	FP	且	占	FP	단 l	FР	BR	<u> </u>	4 0	L 0	BR	BR	FP	FP	BR	FP	ЬP	단	FP	FP	<u></u>	<u></u>	단	FP	ЬP	ב
Туре	Mow	Mow	Mow	Mow	Mow	Mow	Mow	Strim	Mow	Strim	Mow	Strim	Strim	Strim	Mow	Mow	Mow	Mow	Mow	Mow	Strim	Strim	Mow	Mow	Mow	Strim	Strim	Mow	Mow	Mow	Mow	Mow	Strim	Mow	Mow	Strim	Mow	mow	strim	Mow	Mow	Strim	Mow	Mow	
Parish & Path	Kimpton 001	Kimpton 002	Kimpton 004	Kimpton 005	Kimpton 006	Kimpton 007	Kimpton 008A	Kimpton 008B	Kimpton 010	Kimpton 011	Kimpton 012	Kimpton 013	Kimpton 014	Kimpton 017	Kimpton 022	Kimpton 023W	Kimpton 023E	Kimpton 024	Kimpton 026	Kimpton 026	Kimpton 026	Kimpton 026	Kimpton 027	Kimpton 028	Kimpton 029	Kimpton 033	Kimpton 034	Kimpton 035	Kimpton 038	Kimpton 039S	Kimpton 039N	Kimpton 040W	Kimpton 040E	Kimpton 041	Kimpton 042	Kimpton 044	Kimpton 045	Kimpton 047	Kimpton 048	Kimpton 048	Kimpton 048	Kimpton 048	Kimpton 054	Kimpton 058	Kimpton 061